

<p>1</p>	<p>2</p>										
<p>3</p>	<table border="1"> <tr> <td data-bbox="802 1167 1150 1361"> <p>Ax1</p> </td> <td data-bbox="1150 1167 1497 1361"> <p>Bx1</p> </td> </tr> <tr> <td data-bbox="802 1361 1150 1556"> <p>Cx1</p> </td> <td data-bbox="1150 1361 1497 1556"> <p>Dx2</p> <p>M6x16mm</p> </td> </tr> <tr> <td data-bbox="802 1556 1150 1751"> <p>Ex2</p> <p>M8x30mm</p> </td> <td data-bbox="1150 1556 1497 1751"> <p>Fx2</p> <p>M6x25mm</p> </td> </tr> <tr> <td data-bbox="802 1751 1150 1946"> <p>Gx2</p> </td> <td data-bbox="1150 1751 1497 1946"> <p>Hx4</p> </td> </tr> <tr> <td data-bbox="802 1946 1150 2141"> <p>Ix1</p> </td> <td data-bbox="1150 1946 1497 2141"></td> </tr> </table>	<p>Ax1</p>	<p>Bx1</p>	<p>Cx1</p>	<p>Dx2</p> <p>M6x16mm</p>	<p>Ex2</p> <p>M8x30mm</p>	<p>Fx2</p> <p>M6x25mm</p>	<p>Gx2</p>	<p>Hx4</p>	<p>Ix1</p>	
<p>Ax1</p>	<p>Bx1</p>										
<p>Cx1</p>	<p>Dx2</p> <p>M6x16mm</p>										
<p>Ex2</p> <p>M8x30mm</p>	<p>Fx2</p> <p>M6x25mm</p>										
<p>Gx2</p>	<p>Hx4</p>										
<p>Ix1</p>											